



"When Only the Best is Good Enough"



## **CARGO LIFTING NETS**

- Place object in the "orange" centering strips
- Connect all four links to one common hook
- Ensure the object being lifted will not damage the net
- Ensure the object being lifted does not exceed the nets capacity
- Inspect the net before AND after each use.

### **Removal from Service Criteria- Web Slings**



### **DOL-OSHA 29 CFR 1910.184 AND GUIDANCE ON SAFE SLING USE**

Make a thorough inspection of slings and attachments. Items to look for include:

- Missing or illegible sling identification.
- Acid or caustic burns.
- Melting or charring of any part of the sling.
- Holes, tears, cuts or snags.
- Broken or worn stitching in load bearing splices.
- Excessive abrasive wear.
- Knots in any part of the sling.
- Discoloration and brittle or stiff areas on any part of the sling.
- Pitted, corroded, cracked, bent, twisted, gouged or broken fittings.
- Other conditions that cause doubt as to continued use of a sling.

Where any such damage or deterioration is present, remove the sling or attachment from service immediately.

LIFT-IT MANUFACTURING COMPANY, INC.

1603 West 2nd Street • Pomona, CA 91766 • (909) 469-2251 • FAX (909) 469-2252

email: [info@lift-it.com](mailto:info@lift-it.com) • Website: [www.lift-it.com](http://www.lift-it.com)

**SLINGMAX**®

